# Technical Information Ceracore USC30

Process pressure measurement



# Capacitive, ceramic pressure sensor

# Application

Pressure sensor for use in the pressure measurement of liquid and gaseous media.  $\,$ 

### Your benefits

Dry capacitive ceramic sensor with ultrapure (99.9 %)  $\rm Al_2O_3$  ceramic

- High overload resistance
- Very good long-term stability
- High corrosion resistance
- Digital/analog signal output (SPI, UART, U)
- Small physical size
- Measuring ranges from 0 to 0.1 bar (0 to 1.5 psi) to 0 to 100 bar (0 to 1500 psi)
- Optional temperature output, switch output



# Table of contents

About this document3
Document function 3 Symbols used 3
Function and system design4
Measuring principle 4
CARMEN 4
Intended use
Input
Measured process variable 6
Measuring range 6
Power supply7
Supply voltage
Current consumption
Sensor connection
Output8
Output signal
Signal range and signal on alarm of voltage output 8
Behavior in the event of an error
Dead time, time constant
Dynamic behavior 9
Damping 9
Noise filter
Switch-on time and Warm-up period
Performance characteristics 10
Performance characteristics       10         Reference operating conditions       10
Reference operating conditions       10         Reference accuracy       10
Reference operating conditions       10         Reference accuracy       10         Long-term stability       10
Reference operating conditions       10         Reference accuracy       10
Reference operating conditions       10         Reference accuracy       10         Long-term stability       10
Reference operating conditions       10         Reference accuracy       10         Long-term stability       10         Total Error Band (TEB)       10
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Installation conditions 13 Installation conditions 13
Reference operating conditions
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Installation conditions 13 Installation conditions 13
Reference operating conditions
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Influence of the installation position 13 Installation conditions 13 Handling sensors with reference air tube (optional) 13 Safety notes 13
Reference operating conditions
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Influence of the installation position 13 Installation conditions 13 Handling sensors with reference air tube (optional) 13 Safety notes 13  Process and environment 14 Process and ambient temperature range 14 Storage temperature range 14 Degree of protection 14 Climate class 14 Electromagnetic compatibility (EMC) 14 Overvoltage protection 14
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Influence of the installation position 13 Installation conditions 13 Handling sensors with reference air tube (optional) 13 Safety notes 13  Process and environment 14 Process and ambient temperature range 14 Storage temperature range 14 Degree of protection 14 Climate class 14 Climate class 14 Overvoltage protection 14 Overvoltage protection 15  Mechanical construction 15
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Influence of the installation position 13 Installation conditions 13 Handling sensors with reference air tube (optional) 13 Safety notes 13  Process and environment 14 Process and ambient temperature range 14 Storage temperature range 14 Degree of protection 14 Climate class 14 Electromagnetic compatibility (EMC) 14 Overvoltage protection 15  Mechanical construction 15 Device dimensions 15
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Influence of the installation position 13 Installation conditions 13 Handling sensors with reference air tube (optional) 13 Safety notes 13  Process and environment 14 Process and ambient temperature range 14 Storage temperature range 14 Degree of protection 14 Climate class 14 Climate class 14 Overvoltage protection 14 Overvoltage protection 15  Mechanical construction 15
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Influence of the installation position 13 Installation conditions 13 Handling sensors with reference air tube (optional) 13 Safety notes 13  Process and environment 14 Process and ambient temperature range 14 Storage temperature range 14 Climate class 14 Electromagnetic compatibility (EMC) 14 Overvoltage protection 14  Mechanical construction 15 Maintenance and cleaning 16  Maintenance and cleaning 16
Reference operating conditions 10 Reference accuracy 10 Long-term stability 10 Total Error Band (TEB) 10  Installation 13 Influence of the installation position 13 Installation conditions 13 Handling sensors with reference air tube (optional) 13 Safety notes 13  Process and environment 14 Process and ambient temperature range 14 Storage temperature range 14 Climate class 14 Climate class 14 Climate class 14 Climate class 15 Relectromagnetic compatibility (EMC) 14 Overvoltage protection 15 Mechanical construction 15 Device dimensions 15 Materials 15

Certificates and approvals	16
RoHS	16
Other standards and guidelines	
Calibration; unit	
Ordering information	17
Disposal	17
Accessories	18
Built-in components	18
O-ring	18
Cable	18
Contact addresses	18
Explanations and supplementary documentation	19
Terms and abbreviations	
Turn down calculation	20
Supplementary documentation	
CARMEN sensor settings	20

# About this document

# **Document function**

This document contains all the technical data for the device and provides an overview of the device versions and accessories that can be ordered.

# Symbols used

# Safety symbols

Symbol	Meaning
<b>A</b> WARNING	<b>WARNING!</b> This symbol alerts you to a dangerous situation. Failure to avoid this situation can result in serious or fatal injury.
NOTICE	<b>NOTICE!</b> This symbol contains information on procedures and other facts which do not result in personal injury.

# Symbols for certain types of information

Symbol	Meaning			
Tip Indicates additional information.				
Reference to documentation				
Reference to page				

# Symbols in graphics


Symbol	Meaning
1, 2, 3,	Item numbers
A, B, C,	Views

# Function and system design

#### Measuring principle

A capacitive ceramic sensor element is at the core of the USC30. The basic material is  $(Al_2O_3)$ , an ultrapure (99.9 %) aluminum oxide ceramic that is highly resistant to many aggressive gases and liquids. Two cylindrical ceramic components (process isolating diaphragm and ceramic substrate) are hermetically sealed together. In the case of absolute pressure sensors, the reference vacuum of  $3.0 \times 10^{-6}$  mbar that is generated in the production process between the process isolating diaphragm and the ceramic substrate becomes permanent, thereby enabling precise pressure measurement relative to the vacuum. In the case of gauge pressure sensors, the back of the process isolating diaphragm is ventilated, i.e. this sensor measures the gauge pressure relative to the atmospheric pressure.

In electrical terms, the sensor element represents a plate capacitor whose change in capacitance is a measure for the change in pressure. The capacitive measurement method satisfies the highest requirements with regard to resolution and reproducibility. Together with the hysteresis-free behavior of the  $Al_2O_3$  material, it forms the basis for the excellent technical specifications of the pressure sensor. Furthermore, the sensor element is a dry measuring cell, i.e. there is no separating diaphragm or oil filling which could influence the measurement. Another advantage of the capacitive ceramic sensor is its high overload resistance.



- A Gauge pressure cell
- B Absolute pressure cell
- Cr electrode
- 2 Cp electrode
- Brazing ring preform
- Counterelectrode
- 5 Ceramic substrate
- 6 Process isolating diaphragm
- p Process pressure
- p<sub>atm</sub>Atmospheric pressure

#### **CARMEN**

The CARMEN ASIC is used in sensor applications to measure physical variables (e.g. pressure) with external capacitive or resistive sensors in industrial environments.

Each sensor has its individual properties. CARMEN compensates for these physical properties individually. To do so, CARMEN performs the following steps:

- Measurement of the external sensor (capacitance difference, voltage difference, temperature)
- Compensation of the sensor offset
- Gain adjustment
- Linearization of the sensor characteristics
- Compensation of temperature effects
- Output of the corrected and compensated measured values
- Additional functions (damping, filtering, etc.)

For the standard settings of the sensor,  $\rightarrow \stackrel{\triangleright}{=} 20$ .

The functionality and communication are explained in the S&C CARMEN Manual.

### Intended use

The Ceracore USC30 is a pressure sensor used for pressure and level measurement.

# Integration into an overall system

The Ceracore USC30 is a component. Installation and commissioning in an overall system must be carried out in accordance with the technical regulations and by qualified specialist personnel.

### Incorrect use

The manufacturer is not liable for damage caused by improper or non-intended use.

### Clarification for borderline cases

For special process media and fluids for cleaning:

Endress+Hauser is glad to provide assistance in verifying the corrosion resistance of fluid-wetted materials, but does not accept any warranty or liability.

# Input

Measured process variable

- Gauge pressure or absolute pressure
- Temperature

# Measuring range

Sensor	Maximum sensor measurin	g range	Lowest calibratable span	MWP	OPL	Vacuum resistance
	lower (LRL)	upper (URL)				
[bar (psi)]	[bar (psi)]	[bar (psi)]	[bar (psi)]	[bar (psi)]	[bar (psi)]	[bar <sub>abs</sub> (psi <sub>abs</sub> )]
Sensors for gaug	e pressure measur	rement				
0.1 (1.5)	-0.1 (-1.5)	+0.1 (+1.5)	0.02 (0.3)	2.7 (40.5)	4 (60)	0.7 (10.5)
0.2 (3)	-0.2 (-3)	+0.2 (+3)	0.04 (0.6)	3.3 (49.5)	5 (75)	0
0.4 (6)	-0.4 (-6)	+0.4 (+6)	0.08 (1.2)	4 (60)	6 (90)	0
1 (15)	-1 (-15)	+1 (+15)	0.2 (3)	6.7 (100.5)	10 (150)	0
2 (30)	-1 (-15)	+2 (+30)	0.4 (6)	12 (180)	18 (270)	0
4 (60)	-1 (-15)	+4 (+60)	0.8 (12)	16.7 (250.5)	25 (375)	0
10 (150)	-1 (-15)	+10 (+150)	2 (30)	26.7 (400.5)	40 (600)	0
20 (300)	-1 (-15)	+20 (+300)	4 (60)	26.7 (400.5)	40 (600)	0
40 (600)	-1 (-15)	+40 (+600)	8 (120)	40 (600)	60 (900)	0
100 (1500)	-1 (-15)	+100 (+1500)	20 (300)	100 (1500)	150 (2250)	0
Sensors for abso	lute pressure mea	surement				
0.1 (1.5)	0	+0.1 (+1.5)	0.02 (0.3)	2.7 (40.5)	4 (60)	0
0.2 (3)	0	+0.2 (+3)	0.04 (0.6)	3.3 (49.5)	5 (75)	0
0.4 (6)	0	+0.4 (+6)	0.08 (1.2)	4 (60)	6 (90)	0
1 (15)	0	+1 (+15)	0.2 (3)	6.7 (100.5)	10 (150)	0
2 (30)	0	+2 (+30)	0.4 (6)	12 (180)	18 (270)	0
4 (60)	0	+4 (+60)	0.8 (12)	16.7 (250.5)	25 (375)	0
10 (150)	0	+10 (+150)	2 (30)	26.7 (400.5)	40 (600)	0
20 (300)	0	+20 (+300)	4 (60)	26.7 (400.5)	40 (600)	0
40 (600)	0	+40 (+600)	8 (120)	40 (600)	60 (900)	0
100 (1500)	0	+100 (+1500)	20 (300)	100 (1500)	150 (2250)	0

# **▲** WARNING

The maximum pressure for the measuring device depends on the lowest-rated element with regard to pressure.

► The measuring device must be operated only within the specified limits!

# Power supply

# Supply voltage

Туре	Value
Digital output, Analog output	2.9 to 5.5 V DC

# **Current consumption**

< 1.6 mA

### Sensor connection

# NOTICE

Incorrect polarity can damage the ASIC!

► Ensure polarity is correct.


# NOTICE

Incorrect analog measured value due to cable break from GND!

Prevent cable break from GND.

# Female header strip 2x5 pins (1.27 mm (0.05 in) spacing)

Socket type: SAMTEC SFML-105-02-L-D
 Insertion force (axial only): max. 40 N



imgdf1\_

PIN Designation		tion Explanation		Application		
			Digital		Analog	
			UART	SPI	-	
1	GND	Negative supply voltage	X	Х	Х	
2	RESET_N	Reset (low active)	optional	optional	optional	
3	VDD	Positive supply voltage	X	Х	Х	
4	DAC	Analog output (Digital to analog converter)	optional	optional	optional	
5	SW_OUT	Switch output (open drain)	optional	optional	optional	
6	SPI_SEL	Communication mode selection (UART "GND" or SPI "VDD")	force to "GND"	force to "VDD"	force to "GND"	
7	SCK	SPI clock, must be connected to GND if SPI is not used	-	Х	_	
8	CS_N	Chip select (low active)	optional	optional	-	
9	TxD/SO_RDY	Digital communication output	X	X	-	
10	RxD/SI	Digital communication input, must be connected to GND if not used	X	X	force to "GND"	

# NOTICE

# Damage to the plug!

► The SAMTEC plug is fixed to the socket using the locking mechanism. To avoid damage, the plug should not be disconnected again.


# **Output**

# Output signal

Туре	Output	
Voltage output (pressure) 1)	10 to 90 % VDD (ratiometric, VDD = 5.0 V DC)	
Digital output (pressure & temperature) 2)	SPI	
	UART	
Switch output (pressure) 3)	Switch (via CARMEN)	

- 1) Max. load: min. 1 M $\Omega$ , max. 1 nF
- 2) Temperature signal when ordering the additional output, Temperature oC (on chip) in  $^{\circ}$ C
- 3) On request

# Signal range and signal on alarm of voltage output



- 1 Calibrated measuring range
- 2 Extended measuring range


The error value of the signal on alarm can be configured and is displayed in the illustration for the example > 95 % VDD (CARMEN standard sensor setting).

# Behavior in the event of an error

See the S&C CARMEN Manual

# Dead time, time constant

Presentation of the dead time and the time constant:



1 % of the measured value

t time

# Dynamic behavior

Output	Sampling rate [ms]	Dead time (t <sub>1</sub> ) [ms]	Time constant T63 (t <sub>2</sub> ) [ms]	Time constant T90 (t <sub>3</sub> ) [ms]	Time constant T99 (t <sub>4</sub> ) [ms]
Digital	20	40	34	48	59
	5	10	8.5	12	15
	1.25 <sup>1)</sup>	3.75	2.25	3.25	4.25
Analog	20	29	34	46	59
	5	8	7.5	11	14
	1.25	2	2.5	4	6.5

<sup>1)</sup> The maximum sampling rate that can be configured for measured value recording is 1.25 ms, but the maximum speed of the digital output is limited to 2.5 ms.

Damping	Customizable setting: 0 to 40 s
Noise filter	A noise filter is optionally available as a sensor add-on function (see S&C CARMEN Customer Manual).
Switch-on time and Warm-up period	The switch-on time is the time that elapses from when the supply voltage is switched on to when the first digital value or initial analog value is available.

The warm-up period is the time that elapses from when the supply voltage is switched on to the first digital measured value or analog value within the specified reference accuracy (e.g. 0.1% span).

Output	Sampling rate [ms]	Switch-on time [ms]	Warm-up period [ms]
Digital	20	38.75	98.75
	5	23.75	38.75
	1.25	20	23.75
Analog	20	10	50
	5	10	35
	1.25	10	30

# Performance characteristics

# Reference operating conditions

- As per DIN EN IEC 62828
- Ambient temperature  $T_A$  = constant, in range: +23 to +27 °C (+73 to +81 °F)
- Relative humidity  $\varphi$  = constant, in range: 5 to 80 % RH.
- Ambient pressure  $p_A$  = constant, in range: 860 to 1 060 mbar (12.47 to 15.37 psi)
- Position of measuring cell = constant, in range: process isolating diaphragm pointing downwards (see also the "Influence of installation position" section → 13)
- Voltage output supply voltage: 4.9 to 5.1 V DC
- Digital output supply voltage: 2.9 to 5.5 V DC
- Reference installation of Endress+Hauser (Components and Mounting instructions SD02471P)

#### Reference accuracy

The reference accuracy includes the terminal-based non-linearity, the non-repeatability and the pressure hysteresis according to [DIN EN IEC 62828-1].

Sensor	Reference accuracy in % of calibrated span
Platinum	±0.1 x TD for TD <sup>1)</sup> 1:1 to TD 5:1


1) TD = Turn Down,  $\rightarrow 20$ .

### Long-term stability

 $\leq$  0.1 %/year related to the upper range limit (URL).

### **Total Error Band (TEB)**


The Total Error Band includes the following influencing factors:



Total Error Band Einflussfaktoren E

# **Total Error Band**


- Sensor measuring range: 0.1 to 0.4 bar (1.5 to 6 psi)
   Process temperature: -40 to +125 °C (-40 to +257 °F)



	Error in % of the calibrated span	
Temperature range	Typical value	Maximum value
0 to +60 °C (+32 to +140 °F)	± 0.15 x TD	± 0.30 x TD
-40 to 0 °C (-40 to +32 °F) +60 to +80 °C (+140 to +176 °F)	± 0.25 x TD	± 0.50 x TD
+80 to +125 °C (+176 to +257 °F)	± 0.6 x TD	± 1.5 x TD

### **Total Error Band**

- Sensor measuring range: 1 to 100 bar (15 to 1500 psi) Process temperature: -40 to +125 °C (-40 to +257 °F)




Error in % of the calibrated span Typical value Maximum value Temperature range 0 to +60 °C (+32 to +140 °F) ± 0.10 x TD ± 0.20 x TD -40 to 0 °C (-40 to +32 °F)  $\pm$  0.15 x TD ± 0.30 x TD +60 to +80 °C (+140 to +176 °F) +80 to +125 °C (+176 to +257 °F) ± 0.35 x TD ± 1.5 x TD

# Installation

# Influence of the installation position

Any installation position is possible but it may cause a zero point shift.



img296\_

	Process isolating diaphragm pointing downwards (A)	Process isolating diaphragm axis is horizontal (B)	Process isolating diaphragm pointing upwards (C)
<1 bar (15 psi)	Reference position, no effect	Up to +0.1 mbar (0.0015 psi)	Up to +0.2 mbar (0.0030 psi)
≥1 bar (15 psi)	Reference position, no effect	<0.1 mbar (0.0015 psi)	Up to +0.1 mbar (0.0015 psi)

### Installation conditions

- During installation, electrical connection and operation, no moisture may penetrate the device.
- The back of the sensor element must not be encapsulated.

# Handling sensors with reference air tube (optional)

# NOTICE

Danger of damaging the device!

- ► Handle with care.
- ▶ Do not bend, shear or pull reference air tube.

# Safety notes

For work on and with the device:





Danger of damaging the device!

Static sensitive devices.

Handle only at static safe work stations!

# **Process and environment**


Process and ambient temperature range	-40 to $+125$ °C ( $-40$ to $+257$ °F) Compensated range $-20$ to $+80$ °C ( $-4$ to $+176$ °F)			
Storage temperature range	-40 to +125 °C (−40 to	-40 to +125 °C (−40 to +257 °F)		
Degree of protection	System		Dogwoo of protoction	
-	System		Degree of protection	
	Open		IP00 (indoor use)	
Climate class	System	Climate class	Note	
	Open	3K22 (formerly 3K3)	Air temperature: 5 to 40 °C (41 to 104 °F), relative humidity: 5 to 85 % satisfied according to 60721-3-3 (condensation not permitted)	

Electromagnetic compatibility (EMC) No specifications (open system)

6 V DC (maximum voltage for CARMEN ASIC) Overvoltage protection

# Mechanical construction

# **Device dimensions**



The reference air tube is optionally available for sensors for relative pressure measurement.

Sensor [bar (psi)]	Y [mm]	Z [mm]
0.1 (1.5)	5.13	12.88
0.2 (3)	5.16	12.91
0.4 (6)	5.19	12.94
1 (15)	5.24	12.99
2 (30)	5.3	13.05
4 (60)	5.37	13.12
10 (150)	5.51	13.26
20 (300)	5.63	13.38
40 (600)	5.78	13.53
100 (1500)	6.13	13.88

# Materials

# Materials in contact with process

Component part	Material
Process isolating diaphragm	${\rm Al_2O_3}$ aluminium oxide ceramic FDA, ultra-pure 99.9 % $^{1)}$

1) The US Food & Drug Administration (FDA) has no objections to the use of ceramics made of aluminum oxide as a surface material in contact with foodstuffs. This declaration is based on the FDA certificates of our ceramic suppliers.

### Materials not in contact with process

Component part	Material
Reference air tube	Brass CW508L

TSE free (Transmissible Spongiform Encephalopathy)

The following applies to all device components in contact with the process:

- They do not contain any materials derived from animals.
- No additives or operating materials derived from animals are used in production or processing.

# Maintenance and cleaning

#### Maintenance

No special maintenance work is required.

### Exterior cleaning

Please note the following when cleaning the sensor:

- The cleaning agents used should not corrode the surfaces and the seals
- Mechanical damage to the process diaphragm, e.g. caused by sharp objects, must be avoided
- Observe the degree of protection of the device

# Certificates and approvals

#### RoHS

The measuring system complies with the substance restrictions of the Restriction on Hazardous Substances Directive 2011/65/EU.

# Other standards and guidelines

The applicable European guidelines and standards can be found in the relevant EU Declarations of Conformity. The following were also applied:

# DIN EN IEC 62828-1, 62828-2:

Reference conditions and procedures for testing industrial and process measurement transmitters

Part 1: General procedures for all types of transmitters

Part 2: Specific procedures for pressure transmitters

### DIN 16086:

Electrical pressure measuring instruments, pressure sensors, pressure transmitters, pressure measuring instruments, concepts, specifications on data sheets.

Procedure for writing specifications in data sheets for electrical pressure measuring instruments, pressure sensors and pressure transmitters.

# EN 61010-1 (IEC 61010-1):

Protection Measures for Electrical Equipment for Measurement, Control, Regulation and Laboratory Equipment

### Calibration; unit

Designation
Nominal range; mbar
Nominal range; bar
Nominal range; psi
Nominal range; Pa
Nominal range; kPa
Nominal range; MPa
Nominal range; mmH <sub>2</sub> O
Nominal range; mH <sub>2</sub> O
Nominal range; inH <sub>2</sub> O
Nominal range; ftH <sub>2</sub> O
Nominal range; mmHg

# Ordering information

Detailed ordering information is available from the following sources: In the Product Configurator on the Endress+Hauser website: www.sensors-components.endress.com



# $\label{lem:configuration} \textbf{Product Configurator - the tool for individual product configuration}$

- Product-specific configuration data
- Depending on the device: direct input of information specific to measuring point, such as measuring range
- Automatic verification of exclusion criteria

# **Disposal**



According to the Directive 2012/19/EU on waste electrical and electronic equipment (WEEE), our products are marked with the depicted symbol in order to minimize the disposal of WEEE as unsorted municipal waste. Such products may not be disposed of as unsorted municipal waste and can be returned to Endress+Hauser for disposal at conditions stipulated in our General Terms and Conditions or as individually agreed.

# Accessories

# **Built-in components**

Component	Notes	Туре	Measuring range	Process temperature range
L-ring	See mounting instructions SD02471P position 1	Basic	up to 40 bar (600 psi)	-40 to +80 °C (-40 to +176 °F)
		Extended	up to 100 bar (1500 psi)	-40 to +125 °C (-40 to +257 °F)
PTFE foil	See mounting instructions SD02471P position 4		up to 100 bar (1500 psi)	-40 to +125 °C (-40 to +257 °F)
Ceramic ring	See mounting instructions SD02471P position 5		up to 100 bar (1500 psi)	-40 to +125 °C (-40 to +257 °F)
Pressure ring	See mounting instructions SD02471P position 6	Basic	up to 40 bar (600 psi)	-40 to +80 °C (-40 to +176 °F)
		Extended	up to 100 bar (1500 psi)	-40 to +125 °C (-40 to +257 °F)
Thread ring	See mounting instructions SD02471P position 7		up to 100 bar (1500 psi)	-40 to +125 °C (-40 to +257 °F)

# O-ring

Туре	Notes	Measuring range	Process temperature range
FKM	-	up to 10 bar (150 psi)	-40 to +125 °C (-40 to +257 °F)
		up to 40 bar (600 psi)	-30 to +125 °C (-22 to +257 °F)
FKM, FDA	FDA21 CFR177.2600 USP Class VI 3A; BAM	up to 40 bar (600 psi)	0 to +80 °C (+32 to +176 °F)
		up to 100 bar (1500 psi)	+25 to +80 °C (+77 to +176 °F)
EPDM	FDA21 CFR177.2600 USP Class VI (up to +70 °C (+158 °F)) 3A DVGW (W270, W534), WRAS, ACS NSF61	up to 40 bar (600 psi)	-20 to +125 °C (-4 to +257 °F)
NBR	-	up to 20 bar (300 psi)	-40 to +110 °C (-40 to +230 °F)
		up to 100 bar (1500 psi)	-20 to +110 °C (-4 to +230 °F)

# Cable

Туре	Process temperature range
Adapter cable for female header strip 2x5 pins (1.27 mm (0.05 in) spacing), Mating connector for SAMTEC	−10 to +80 °C (+14 to +176 °F)

# **Contact addresses**


Internet: www.sensors-components.endress.com E-mail: sensors-components.ehlp@endress.com

# Adress:

Endress+Hauser SE+Co. KG Sensors & Components Hauptstraße 1 79689 Maulburg Germany


# **Explanations and supplementary documentation**

#### Terms and abbreviations



Item Term/abbreviation **Explanation** OPI. The OPL (over pressure limit = sensor overload limit) for the measuring device depends on the lowest-rated element, with regard to pressure, of the selected components, i.e. the process connection has to be taken into consideration in addition to the measuring cell. Also observe pressure-temperature dependency. The test pressure corresponds to the overload limit of the sensor ( $OPL = 1.5 \times MWP$ ) and may only be applied for a limited period of time so that no permanent damage occurs. **MWP** The MWP (maximum working pressure) for the sensors depends on the lowest-rated element, with regard to pressure, of the selected components, i.e. the process connection has to be taken into consideration in addition to the measuring cell. Also observe pressure-temperature dependency. The Pressure Equipment Directive (2014/68/EU) uses the abbreviation "PS", which corresponds to the MWP of the measuring instrument. The MWP refers to a reference temperature of +20  $^{\circ}$ C (+68  $^{\circ}$ F) and may be applied at the device for an unlimited period. Span between LRL and URL Maximum sensor measuring range This sensor measuring range is equivalent to the maximum calibratable/adjustable span. Calibrated/adjusted Span between LRV and URV Default setting: 0 to URL span Other calibrated spans can be ordered as customized spans. Pressure p LRL Lower range limit URL Upper range limit LRV Lower range value URV Upper range value Turn Down Example - see the following section. CARMEN Capacitive And Resistive Measurement ENdress+Hauser  $\rightarrow \stackrel{\triangle}{} 4$ Sampling rate The sampling rate is the integration time for recording the measured value and also the update interval for the output of measured values. Exception: If a sampling rate of  $1.25~\mathrm{ms}$  is configured, the integration time is  $1.25~\mathrm{ms}$  but the update interval ASIC Application-specific integrated circuit

# Turn down calculation



- Calibrated/adjusted span Upper range limit

# Example • Sensor: 10 bar (150 psi)

- Upper range limit (URL) = 10 bar (150 psi)
   Lower range limit (LRL) = -1 bar (-15 psi)

• Calibrated/adjusted span: 0 to 5 bar (0 to 75 psi)

- Lower range value (LRV) = 0 bar (0 psi)
- Upper range value (URV) = 5 bar (75 psi)

Turn Down (TD):

In this example, the TD is 2:1.

For TD < 1, the performance characteristics of TD = 1 apply.

# Supplementary documentation

■ Mounting instructions SD02471P

### **CARMEN** sensor settings

Default settings		
Measuring mode	Continuous	
Damping	0	
Analog initial value	< 5 %	
Analog error value	> 95 %	
Analog error behavior (status flags)	0, 1, 4, 5, 9, 10, 15, 17, 18	
Digital error behavior (status flags)	0, 1, 4, 5, 9, 10, 15, 17, 18	
UART baud rate	57.6 kBd	
Digital continuous transmission	Activated	
Switching threshold, on	0 %	
Switching threshold, off	0 %	
Switching delay	0 s	

The sensor setting is configurable, see S&C CARMEN Customer Manual.

